



WILLIAM JOHNSTON & COMPANY LIMITED

Glasgow Tel: +44 (0) 141 620 1666 | Inverness Tel: +44 (0) 1463 238 673
sales@williamjohnston.co.uk | www.williamjohnston.co.uk

EXTRUSIONS IN SILICONE

Disclaimer









Please note, failure to select the correct materials or products we supply (“the Products”) may result in damage to plant, equipment or property. In some instances, it may cause death or personal injury. We are not designers and do not give advice about design related matters concerning the Products. We can help and assist with the technical specifications for the Products. In specific applications, particularly where critical conditions exist, we will try to assist you within the limitations of the services that we offer. All information supplied by us is intended as technical co-operation outlining the specifications of the different Products which we supply. To the extent permitted in law, no warranty is given in respect of any information supplied by us. The customer must satisfy themselves as to the suitability of the Products for their intended application and use. The correct fitting of Products is the responsibility of the customer. Your statutory rights remain unaffected. Save in respect of death, personal injury or fraud, our entire liability to you, however arising from the supply of Products shall be limited to the £10M indemnity amount provided by our insurers.




300°C




D-Hollow




D-Hollow




1675




1669




3863




3862




1666



3865











1283



3604









William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




1231




622




4196




1143




4143



1729




1727




4197

William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




1433




4016




2027




1930




682



4015




4039




1998

William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




819




1406




1764




2129



825




794



Cut length = 85mm
Cut before post cure adding 1mm for shrinkage


1405




1301

William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




869




1929




3754




1478




877



858











809



4387









William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




893




1035




3570




4418




2767



3091











3189



87


William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




4468




2739




316




2783




329



2970











4458



3373









William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow




William Johnston & Company Limited
Tel 0141 620 1666


D-Hollow




3603




4443




2936




2594




4428



412











2505



2517









William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow





William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Hollow











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid




William Johnston & Company Limited
Tel 0141 620 1666

D-Solid




William Johnston & Company Limited
Tel 0141 620 1666


D-Solid




2033




2091




2359




2087



2000



3592











1023



1









William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid











William Johnston & Company Limited
Tel 0141 620 1666

D-Solid




William Johnston & Company Limited
Tel 0141 620 1666

D-Solid




William Johnston & Company Limited
Tel 0141 620 1666

D-Solid




William Johnston & Company Limited
Tel 0141 620 1666


E-Section




644




3395




2603




4451




2617



3376











3344



2657









William Johnston & Company Limited
Tel 0141 620 1666

E-Section











William Johnston & Company Limited
Tel 0141 620 1666

E-Section











William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666


E-Section




177




1900




178




3236




4233



1992











207



4469









William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666


E-Section




4365




1739




1093




4059




93



1373











1180



4364









William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666


E-Section




3800




3000




3160




1047




1841



1850











3793



1118









William Johnston & Company Limited
Tel 0141 620 1666

E-Section











William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666

E-Section




William Johnston & Company Limited
Tel 0141 620 1666


E-Section




3920




4114




1173



1033




1605




4334

William Johnston & Company Limited
Tel 0141 620 1666


H-section




4078




4087




577




2231




3881



4061











4294



4295









William Johnston & Company Limited
Tel 0141 620 1666

H-section











William Johnston & Company Limited
Tel 0141 620 1666

H-section











William Johnston & Company Limited
Tel 0141 620 1666

H-section




William Johnston & Company Limited
Tel 0141 620 1666

H-section




William Johnston & Company Limited
Tel 0141 620 1666


H-section




3629




4086




4277




1971




4536



1756




4163




3658

William Johnston & Company Limited
Tel 0141 620 1666


H-section




3833




4146




2976




3682




3738



4158






4036



4509


William Johnston & Company Limited
Tel 0141 620 1666

H-section




William Johnston & Company Limited
Tel 0141 620 1666


Hollow Strip




1641




639




4130




3956




3683



1820











1872



2899








William Johnston & Company Limited
Tel 0141 620 1666

Hollow Strip











William Johnston & Company Limited
Tel 0141 620 1666

Hollow Strip











William Johnston & Company Limited
Tel 0141 620 1666

Hollow Strip




William Johnston & Company Limited
Tel 0141 620 1666

Hollow Strip




William Johnston & Company Limited
Tel 0141 620 1666


Hollow Strip




4256




80




3980




1827




300



1828









1272



2468









William Johnston & Company Limited
Tel 0141 620 1666

Hollow Strip











William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal











William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal











William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666


Inflatable-seal




3813




2026




2668




4234




4009



3824




2207




2881

William Johnston & Company Limited
Tel 0141 620 1666


Inflatable-seal




2023




2382




3105




2417




2416



4188











2672



2792









William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666


Inflatable-seal




2068




3425




3385




1356




2733



3166











3999



2058


William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666


Inflatable-seal




4055




1649




2227




2130




2150



2565




2158




4133

William Johnston & Company Limited
Tel 0141 620 1666


Inflatable-seal




3210




4058




1067




4257




2179



2157




3037



1674


William Johnston & Company Limited
Tel 0141 620 1666

Inflatable-seal




William Johnston & Company Limited
Tel 0141 620 1666


L-Section




4340




1022




2680




2699




4017



4023











4027



1722









William Johnston & Company Limited
Tel 0141 620 1666

L-Section




William Johnston & Company Limited
Tel 0141 620 1666

L-Section




William Johnston & Company Limited
Tel 0141 620 1666


L-Section




1577




1157




2712




1095




753



4242











4147



1411


William Johnston & Company Limited
Tel 0141 620 1666

L-Section




William Johnston & Company Limited
Tel 0141 620 1666


L-Section




3631




3797




238




4398




4439



404











410



456









William Johnston & Company Limited
Tel 0141 620 1666

L-Section









William Johnston & Company Limited
Tel 0141 620 1666

L-Section











William Johnston & Company Limited
Tel 0141 620 1666

L-Section











William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666


Autoclave




4447




1999




2152




1921




2775



1915











3281



4363


William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666


Autoclave




2133



4375











1877



4570









William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666


Autoclave




4447




2775




1999




1915




2152



3281











1921



4363





William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666

Autoclave




William Johnston & Company Limited
Tel 0141 620 1666


Glazing




3661




3626




3615




3612



3611











3614



3613


William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4348




21




1635




1618




4347



4381




1620




1617

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




1194




1593




1215




1420




1596



1211




1221




4345

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




1416




1627




1914




957




1932



1922











1888



1875









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




473




2399




2469




2512




2402



2394











2597



2686


William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2511




2385




2463




1957




1281



1282











1526



1523


William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2018




2509




2508




2504




2494



2491











431



2479









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




218




2751




2728




3135




2962



2958











2729



2955









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




1996




1986




2589




115




1988



1975











1683



3072


William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2772




3062




3051




2031




985



1952




1088




1811

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




1803




2219




1782




2773




1791



1784




1781




4531

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4530




3639




4208




4309




3902



3630











3694



4025









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4315




4199




3834




4302




2599



3777




3766




3765

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3227




3225




3226




4207




3665



4034




3577




4395

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3619




3353




3760




3884




3883



4221




4241




3411

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3423




3319




3991




4142




4010



3186




3369




3459

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3567




3959




3262




4250




4247



3323











4002



3549









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal











William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4067




4068




4251




4101




3528



3333




4011




4496

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4523




3556




4065




500




2264



2074











2056



2055


William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2105




2338




2334




505




506



2317











606



2292









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2192




2258




625




2176




2171



2168




2167




2153

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2151




2377




2115




2265




2144



2116











3930



4175









William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666

Lip-Seal




William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




4284




4298




4222




4293




3795



3617




3596




2252

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




2243




2236




2217




2313




2242



2220




2375




3305

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3576




4261




3390




3309




3205



2596




3270




4190

William Johnston & Company Limited
Tel 0141 620 1666


Lip-Seal




3310




4412




3207




3606



3208




4411




3742

William Johnston & Company Limited
Tel 0141 620 1666


Bubble




2449




2287




2481




3371




2270



2741











3846



3820









William Johnston & Company Limited
Tel 0141 620 1666

Bubble





William Johnston & Company Limited
Tel 0141 620 1666

Bubble











William Johnston & Company Limited
Tel 0141 620 1666

Bubble




William Johnston & Company Limited
Tel 0141 620 1666


Bubble




Bubble




3487




2415




3819




4286




3807



3914




3441




4425

William Johnston & Company Limited
Tel 0141 620 1666


Bubble




3489




3246




3266




3108




2889



3130





3841



3096









William Johnston & Company Limited
Tel 0141 620 1666

Bubble




William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole




William Johnston & Company Limited
Tel 0141 620 1666


Key-Hole




3921




3034




787




3190




385



3628











3559



3698


William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole




William Johnston & Company Limited
Tel 0141 620 1666


Key-Hole




351




428




378




2777




4079



1459











4374



4426


William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole




William Johnston & Company Limited
Tel 0141 620 1666


Key-Hole




3946




85




1962




1274




1217



3788











3179



986









William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole











William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole











William Johnston & Company Limited
Tel 0141 620 1666

Key-Hole




William Johnston & Company Limited
Tel 0141 620 1666

Omega




William Johnston & Company Limited
Tel 0141 620 1666


Omega




4352




1583




274




1294




1467



282




2611




1719

William Johnston & Company Limited
Tel 0141 620 1666


Omega




414




2141




111




2501




927



563



1426




Tool Modified 28/09/99


1612

William Johnston & Company Limited
Tel 0141 620 1666


Omega




128




2280




4505




2543




2184



1218









4165



3443









William Johnston & Company Limited
Tel 0141 620 1666

Omega




William Johnston & Company Limited
Tel 0141 620 1666

Tadpole




William Johnston & Company Limited
Tel 0141 620 1666


Tadpole




4459




192




4304




1701




1798



3268




4542




3597

William Johnston & Company Limited
Tel 0141 620 1666


P-Double




1805




3156




191




2755




490



1101











429



2813









William Johnston & Company Limited
Tel 0141 620 1666

P-Double




William Johnston & Company Limited
Tel 0141 620 1666

P-Double




William Johnston & Company Limited
Tel 0141 620 1666


P-Large




1802




1574




2862




2616




813



1631











2820



1599









William Johnston & Company Limited
Tel 0141 620 1666

P-Large











William Johnston & Company Limited
Tel 0141 620 1666

P-Large











William Johnston & Company Limited
Tel 0141 620 1666

P-Large







William Johnston & Company Limited
Tel 0141 620 1666

P-Large




William Johnston & Company Limited
Tel 0141 620 1666

P-Large




William Johnston & Company Limited
Tel 0141 620 1666


P-Medium




2043




1737




3438




19




4033



1471




2314




2959

William Johnston & Company Limited
Tel 0141 620 1666


P-Medium




107




105




114




271




2555



1985











1479



3960









William Johnston & Company Limited
Tel 0141 620 1666

P-Medium











William Johnston & Company Limited
Tel 0141 620 1666

P-Medium











William Johnston & Company Limited
Tel 0141 620 1666

P-Medium











William Johnston & Company Limited
Tel 0141 620 1666

P-Medium











William Johnston & Company Limited
Tel 0141 620 1666

P-Medium




William Johnston & Company Limited
Tel 0141 620 1666

P-Medium




William Johnston & Company Limited
Tel 0141 620 1666


P-Medium




4510




3796




3803




2110




4486



3180











4305



3801






William Johnston & Company Limited
Tel 0141 620 1666

P-Medium




William Johnston & Company Limited
Tel 0141 620 1666

P-Medium




William Johnston & Company Limited
Tel 0141 620 1666


P-Small




955




2916




206




257




1230



253











741



2181









William Johnston & Company Limited
Tel 0141 620 1666

P-Small











William Johnston & Company Limited
Tel 0141 620 1666

P-Small











William Johnston & Company Limited
Tel 0141 620 1666

P-Small




William Johnston & Company Limited
Tel 0141 620 1666

P-Small




William Johnston & Company Limited
Tel 0141 620 1666


P-Small




1052




581




1964




551




4460



110











338



554









William Johnston & Company Limited
Tel 0141 620 1666

P-Small




William Johnston & Company Limited
Tel 0141 620 1666

P-Small











William Johnston & Company Limited
Tel 0141 620 1666

P-Small











William Johnston & Company Limited
Tel 0141 620 1666

P-Solid




William Johnston & Company Limited
Tel 0141 620 1666

P-Solid




William Johnston & Company Limited
Tel 0141 620 1666


P-Solid




782




2696




2531




118



3989











2173



113









William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




388




1692




3686




3458




397



527




4434




1862

William Johnston & Company Limited
Tel 0141 620 1666


T-Section




696




3761




175




4255




3818



174











4427



3645









William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




1468




1070




2383




3932




889



3292




1235




1062

William Johnston & Company Limited
Tel 0141 620 1666


T-Section




3568




3494




2885




4551




934



1397











4176



3558


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




856




4022




1200




4057




4080



3122











3349



3942









William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




3957




1532




1529




3304




3591



994











2397



1509


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




2738




4389




4390




2283




1353



3562




1354



2624









William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




2553




3011




3835




2992




3229



228











2551



2994


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




3633




1711




169




1705




3907



198











2081



1936


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




696




3818




3761




174




175



4427











4255



3645









William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




1968




1950




3715




3695




651



4487











2014



3089









William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




2209




1222




3517




4037




4503



2703











4038



2354


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




3568




3494




2885




4551




934



1397











4176



3558


William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




856




4022




1200




4057




4080



3122











3349



3942









William Johnston & Company Limited
Tel 0141 620 1666

T-Section











William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


T-Section




1891




1189




4420




2121




1878



645




4271




3036

William Johnston & Company Limited
Tel 0141 620 1666


T-Section




1906




3032




3656




4268




2337



433




871




3670

William Johnston & Company Limited
Tel 0141 620 1666


T-Section




3957




1532




1529




3304




3591



994











2397



1509









William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666

T-Section




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




3143




3201




2663




1940




3678



1935











482











2647

U-Large











William Johnston & Company Limited
Tel 0141 620 1666

U-Large











William Johnston & Company Limited
Tel 0141 620 1666

U-Large











William Johnston & Company Limited
Tel 0141 620 1666

U-Large











William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




2016




2627




2007




2072




2628



1762











1994



1995


William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




1622




867




2725




3554




1558



3472











3384



2847


William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




2845




3589




1668




2588




2570



3265











961



2434


William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




876




2758




3484




3897




873



667











2145



2903









William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666

U-Large




William Johnston & Company Limited
Tel 0141 620 1666


U-Large




2843




847




783




2844




660



2569




2926




2841

William Johnston & Company Limited
Tel 0141 620 1666


U-Large




1660




2840




2839



3157











2930



3272









William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




1613




1590




2174




1141




3684



4052




2675




4213

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




2341




4212




1980




3753




1664



3058




1913




2572

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




1942




2754




1375




3124




3125



3673











3602



4403









William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




1642




1644




4441




3518




1355



4513




3768




3675

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




2604




4419




3703




4167




1160



3708











3593



1769


William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




3006




2395




3814




3106




1967



2819




4252




2432

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




2821




1449




3856




3598




2126



4184




1696




4299

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




3668




3837




2108




3963




4203



3238




4186




1096

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




4495




3966




4028




4464




3860



1037




1910




4155

William Johnston & Company Limited
Tel 0141 620 1666


U-Medium




4104




3741




158




1594




1508



1595











4501



4517









William Johnston & Company Limited
Tel 0141 620 1666

U-Medium






William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666

U-Medium




William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




4558




4453




4452




4107




2253



3533











3620



4191


William Johnston & Company Limited
Tel 0141 620 1666

U-Rounded




William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




3867




2857




3318




4220




4353



1976











4507



3664


William Johnston & Company Limited
Tel 0141 620 1666

U-Rounded




William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




2856




941




4465




4178




2107



4195











4289



2166









William Johnston & Company Limited
Tel 0141 620 1666

U-Rounded




William Johnston & Company Limited
Tel 0141 620 1666

U-Rounded




William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




4520




4094




3420




2608




4001



3595




3054




3875

William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




4480




3806




4308




1831




2935



4396




3212




4521

William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




3280




4096




3786




4229




1379



3785




4272




4164

William Johnston & Company Limited
Tel 0141 620 1666


U-Rounded




3627



4013











3953



4134


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1430




1053




2631




3886




4162



1443











3372



2618









William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




U-Small




2344




1333




1248




1244




2718



1241











1240



1239


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




789




1636




1633




3399




865



894











3387



824


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




104




2260




2057




2080




2190



2187











2186



108









William Johnston & Company Limited
Tel 0141 620 1666

U-Small











William Johnston & Company Limited
Tel 0141 620 1666

U-Small











William Johnston & Company Limited
Tel 0141 620 1666

U-Small











William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




2407




170




2379




2303




2195



210











2089



3520









William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1840




509




417




359




1870



616











435



3774









William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




357




346




1731




308




350



4476











1961



289


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1717




306




3713




4482




693



1706




1715




684

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1707




1738




1369




4129




370



1330




2682




1216

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1134




2752




1394




3985




2655



4144











1395



1400


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1413




1081




1310




1300




1286



4070




1297




1304

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




1361




1319




4273




2750




609



615




560




3850

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




4291




4296




3748




626




3070



376




4416




3808

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




4475




4021




3997




1166




389



1949




3337




4385

William Johnston & Company Limited
Tel 0141 620 1666


U-Small




4279




2659




1135




2497




1183



4219





3851



569


William Johnston & Company Limited
Tel 0141 620 1666

U-Small




William Johnston & Company Limited
Tel 0141 620 1666


Arrow-Head




3849




4073




2414




4514




4462



3717











3941



3757


William Johnston & Company Limited
Tel 0141 620 1666

Arrow-Head




William Johnston & Company Limited
Tel 0141 620 1666


Arrow-Head




4048




3939




3158




3783




3812



3642




4455



4019









William Johnston & Company Limited
Tel 0141 620 1666

Arrow-Head











William Johnston & Company Limited
Tel 0141 620 1666

Sponge




William Johnston & Company Limited
Tel 0141 620 1666

Sponge




William Johnston & Company Limited
Tel 0141 620 1666


Sponge




3756




4275




3979




3873




3868



3855











4050



2969




William Johnston & Company Limited
Tel 0141 620 1666

Sponge











William Johnston & Company Limited
Tel 0141 620 1666

Sponge











William Johnston & Company Limited
Tel 0141 620 1666

Square











Square











William Johnston & Company Limited
Tel 0141 620 1666

Square











William Johnston & Company Limited
Tel 0141 620 1666

Square




William Johnston & Company Limited
Tel 0141 620 1666

Square




William Johnston & Company Limited
Tel 0141 620 1666


Square




4548




1321




2025




64




37



1801











39



4232









William Johnston & Company Limited
Tel 0141 620 1666

Square











William Johnston & Company Limited
Tel 0141 620 1666

Square








William Johnston & Company Limited
Tel 0141 620 1666

Square




William Johnston & Company Limited
Tel 0141 620 1666

Square




William Johnston & Company Limited
Tel 0141 620 1666


Trapeze




4238




967




3279




2898




2855



2803




3624




1487

William Johnston & Company Limited
 Tel 0141 620 1666


Trapeze




3278




1749




2118




2822




834



3161











3924



862









William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666


Trapeze




691




1673




3406




1534




726



2917




3407




950

William Johnston & Company Limited
Tel 0141 620 1666


Trapeze




182




1039




2410




1429




1750



3971











3046



476









William Johnston & Company Limited
Tel 0141 620 1666

Trapeze











William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666


Trapeze




4330




1897




1167




2653




1332



529











4346



3088




William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666

Trapeze




William Johnston & Company Limited
Tel 0141 620 1666


Triangle




377




936




676




1041




348



2368











3049




419

Triangle




William Johnston & Company Limited
Tel 0141 620 1666


Triangle




2849




3643




2938




2136




2721



3690











717



728









William Johnston & Company Limited
Tel 0141 620 1666

Triangle











William Johnston & Company Limited
Tel 0141 620 1666

Triangle




William Johnston & Company Limited
Tel 0141 620 1666

Triangle




William Johnston & Company Limited
Tel 0141 620 1666


Triangle




3638




3821




3984




318




1776



610




3584




589

William Johnston & Company Limited
Tel 0141 620 1666


Triangle




3714



2698



3312



1008

Disclaimer

Please note, failure to select the correct materials or products we supply (“the Products”) may result in damage to plant, equipment or property. In some instances, it may cause death or personal injury. We are not designers and do not give advice about design related matters concerning the Products. We can help and assist with the technical specifications for the Products. In specific applications, particularly where critical conditions exist, we will try to assist you within the limitations of the services that we offer. All information supplied by us is intended as technical co-operation outlining the specifications of the different Products which we supply. To the extent permitted in law, no warranty is given in respect of any information supplied by us. The customer must satisfy themselves as to the suitability of the Products for their intended application and use. The correct fitting of Products is the responsibility of the customer. Your statutory rights remain unaffected. Save in respect of death, personal injury or fraud, our entire liability to you, however arising from the supply of Products shall be limited to the £10M indemnity amount provided by our insurers.

William Johnston & Company Limited
Tel 0141 620 1666