

## **WILLIAM JOHNSTON** **& COMPANY LIMITED**



[www.williamjohnston.co.uk](http://www.williamjohnston.co.uk)

Head Office  
9 Spiersbridge Terrace  
Thornliebank Industrial Estate  
Thornliebank  
Glasgow. G46 8JH

[sales@williamjohnston.co.uk](mailto:sales@williamjohnston.co.uk)



+44 (0) 141 620 1666



+44 (0) 141 620 1888

# EXTRUSIONS

# EPDM


# NEOPRENE

# NITRILE




**Underwriters  
Laboratories**


## **FIRE RATED AVAILABLE**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




M167137




MR7540



MS-2024A




MS2359A




MS2632A


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




PW1




Q1516




QL1515-2




R6/9




R25.419




R32.524




R1207




R1309




R1512




R1613




R1875/175




R1913




R2005




R2010




R2011



R2015




R2019




R2310




R2503




R2513




R2514




R2515




R 25,16.5




R2519




R2523




R2714




R2716



R3016




R3016/3




R3020

**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




DT1612




DT 120/60




DT15038




HT 47/26



HT4229




ET3514




DT 150/08


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




DT70706




DT757508




FE10020




HB7040




FE18186



FL2402




G4006




F1


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




GS3005




GS201403




LBS3018




LS5336




LS40A20




L2




L1611




LGS49



J603011




J804011















JP352530

**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**
















**William Johnston & Company Limited**  
**Tel 0141 620 1666**








**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**



LGS11237








LGS10057




LGS50175


**William Johnston & Company Limited**  
**Tel 0141 620 1666**





**William Johnston & Company Limited**  
**Tel 0141 620 1666**




RA1131 OLD SIZE




RA1130 NEW SIZE




Q85858



RB 10015




Q2020




RA15070


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




RG8




RR1409




RR1216




RG6/90




RG7/90




RG4/90




RG5/90




RG1/90




RG2/90




RG3/90




RF1




RFC1922




RT1912




SS5845




SS5845/7




SD6060/18




SD6060




SS3235



SD9345




SU5825




SS4550


**William Johnston & Company Limited**  
**Tel 0141 620 1666**



**William Johnston & Company Limited**  
**Tel 0141 620 1666**











SD18755/MB




SD18755/MT


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**















**William Johnston & Company Limited**  
**Tel 0141 620 1666**




SD18755





















**William Johnston & Company Limited**  
**Tel 0141 620 1666**



**William Johnston & Company Limited**  
**Tel 0141 620 1666**














**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




D5750




D5750/7




D5750/WR




D7546+D6040centre



D7546




D7065





D7040/L

**William Johnston & Company Limited**  
**Tel 0141 620 1666**























**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**



D1003012








D105100




D125110

**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




D5040




D5750/7




D5750/WR




D5750




D5035+D6040centre




D5035SP  
50




D5544




D6040




D4025/SPL




D5015




D5025



D4730H












D4730










D4025





**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




D10892



D10030/6







D10075  
100







D10084


**William Johnston & Company Limited**  
**Tel 0141 620 1666**





**William Johnston & Company Limited**  
**Tel 0141 620 1666**




ADGP 17





ADGP 24/7



DS78







ADGP 22/10




ADGP 22/45


**William Johnston & Company Limited**  
**Tel 0141 620 1666**



**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




LGS3892




LGS301505



LGS10038








LGS9538




LGS9030


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




SQ3030




PH1




RMRP1008




PS3010




WS6080



RS8712




SGS6040





SGS10540

**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




BS4842




C48347




C204990




CF1212




CF1425




CF1510




CL4428H




DB1




DN 7088




DS 1




DS2




DS3



DS1106




DS1507













D150120


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**









**William Johnston & Company Limited**  
**Tel 0141 620 1666**



**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




LS502




LS1504




LC200503




LS1502




LS2608




LS4812




W461310



W361410










ID10580



























ID11282

**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**




CS5012/2.5




CS7033




CS15121.5




CS15122.8




CS16055




CS19255




CS060502




CS080318




CS080414




CS090608




CS090612




CS090619




CS120725




CS191227




CS191315




CS272618




CS160610




CS181307




CS201605




CS231929




CS251603




CS253123




CS161220




CS171305




CS191340




CS191529



CS220633




CS241216




CS252505


**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**




**William Johnston & Company Limited**  
**Tel 0141 620 1666**





**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**















**William Johnston & Company Limited**  
**Tel 0141 620 1666**















**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**















**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**






**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**










**William Johnston & Company Limited**  
**Tel 0141 620 1666**







**William Johnston & Company Limited**  
**Tel 0141 620 1666**





**William Johnston & Company Limited**  
**Tel 0141 620 1666**





**William Johnston & Company Limited**  
**Tel 0141 620 1666**

